

25X1

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

25X1A

## INFORMATION REPORT

COUNTRY Rumania

SUBJECT Port Information: Constanta

25X1A  
PLACE ACQUIRED  
(BY SOURCE)

DATE ACQUIRED  
(BY SOURCE)

DATE (OF INFO.

REPORT NO.

|          |  |
|----------|--|
| RESP     |  |
| 1        |  |
| CD NO.   |  |
| OO/C NO. |  |
| ORR NO.  |  |
| DAS NO.  |  |
| OCI NO.  |  |

DATE DISTR. 5- MAR 1954

NO. OF PAGES 3

NO. OF ENCLS.

SUPP. TO  
REPORT NO.

25X1

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS REPORT IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

2. Chart Designations Coordinated with information reported herein, specific items are cited on overlay to HO Chart 4197 by the following alphabetical designators:

A - Buoy  
B - Approach course line  
C - Boarding point  
D - Pilot disembarked vessel upon departure  
E - Anchorage  
F - Turning area  
G - Source's berth  
H - Soviet tanker  
I - Norwegian tanker  
J - Passenger vessel  
K - Naval small craft berthing

3. Conveyance [ ] visited subject port in a merchant vessel 436' 3" in length, 54' 9" in beam and drawing 26' 6".

4. Approach Vessel approached from seaward on a course of approximately 298° true. First control point was a buoy sighted at designator A. Vessel then proceeded toward the harbor breakwater on a course line designated B.

LAST PAGE FOR CITE REF &amp; ATT. CODES

25X1

ONI review(s)  
completed.

CONFIDENTIAL

| DISTRIBUTION | STATE | ARMY | NAVY | AIR | FBI |  |  |  |  |  |  |
|--------------|-------|------|------|-----|-----|--|--|--|--|--|--|
|--------------|-------|------|------|-----|-----|--|--|--|--|--|--|

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Security.

CONFIDENTIAL/ [REDACTED]

25X1A

25X1

- 2 -

5.

25X1

6. Pilotage Pilots are available and compulsory at all times for entering and clearing, but will not take vessels in at night.

- 25X1 7. Pilotboat [REDACTED] a pilotboat at designator C, which was described as about 40' in length, Diesel drive and of modern construction. The word "PILOT" was written in English on the forward bulkhead of the pilot house. In clearing port, pilot is dropped at designator D.
8. Pilot Pilot boarded vessel with a soldier who was armed with a pistol and guarded him while bringing the ship into port. There was an apparent lack of congeniality between these two individuals as witnessed by fact that when the pilot was offered cigarettes he asked the donor thereof to place them in his coat hanging on the bulkhead, so that the guard could not observe. Pilot spoke English as well as Rumanian, giving orders to the helm in English.
9. Quarantine Anchorage Pilot conducted vessel from boarding point to quarantine anchorage at designator E. At this point doctor and Customs agents cleared the ship to proceed to the petroleum basin.
10. Turning Area The turning area for inner harbor is located at designator F.
11. Tugs Vessel was assisted by a tug while entering port and shifting from anchorage to the petroleum basin. [REDACTED] not hazard a guess as to the power of the tug, but described her as modern, big and of metal construction. He stated tugs are used to assist all vessels.
12. Docking procedure Tug worked vessel into basin stern first. The vessel berthed at designator G, which is on the north side of the petroleum basin.
13. Inspection Party The inspection party boarded the vessel at berth with a force of about 20 persons who conducted a three-hour search of the vessel, with the crew mustered in the messing compartment. The inspection was considered a comprehensive one; cameras, optical equipment and radios were sealed; radar was disconnected and rendered inoperative. The outgoing inspection was of 1½ hours' duration and took place immediately prior to getting underway.
14. Surveillance While at berth, constant surveillance was placed on the vessel by two guards who were stationed alongside. Other soldiers were observed to be quite numerous all over the quay area.
15. Cargo Vessel called port and berthed at the petroleum basin for the purpose of lifting nine thousand long tons of gasoline, light gas-oil and kerosene.
16. Berthing Facility Details Berth was served by about five or six fuel lines located 2' to 3' inboard of the outer edge of the basin. The lines were about 6" in diameter running parallel to the basin and elevated about 7' off the deck. There were no sheds on the quay, and the only handling equipment observed was two fixed booms about three meters long, for the positioning of fuel lines at the seaward extremities of the quay. Arrangement of these features can be noted by the diagram which includes a sketch of the boom itself in the inset.
17. Merchant Shipping Present A Soviet tanker was observed at designator H. She was about 12 thousand gross tons, old, in bad repair, and coal burning. She was lifting a cargo of benzine and gasoline. A Norwegian tanker was berthed at designator I. She was about 14 thousand gross tons, though cargo operations, name or other details were not observed. A modern passenger vessel, about 300' in length and three thousand gross tons was berthed at designator J. [REDACTED]

25X1

CONFIDENTIAL/ [REDACTED]

25X1

CONFIDENTIAL [REDACTED]

25X1A

25X1

- 3 - [REDACTED]

could not be certain whether she was Bulgarian or Rumanian. The ship was apparently idle at present, no activity being noted in her connection.

18. Naval Shipping Present At designator K, four large naval patrol craft and a large tug were located. They were all painted blue and gray and berthed as indicated along the East Breakwater. [REDACTED] could not identify them with anything found in ONI-F-31R. [REDACTED] two of them were about 50' to 60' in length and had one funnel; one was about the same length but had two funnels close to the wheel house; the fourth was about 120' long and had three funnels. No other information was forthcoming.

25X1

- 25X1<sup>19</sup>. Port Efficiency [REDACTED] the delivering of cargo proceeded very slowly, taking about 39 hours to lift nine thousand tons of petroleum products. [REDACTED]  
 25X1 [REDACTED] the Soviet tanker at designator H, described in paragraph 17 supra, was given preferential treatment, being completely loaded and underway in 24 hours.

25X1

- 25X1<sup>20</sup>. Liberty [REDACTED] one-third of the crew was allowed liberty each day. A liberty list had to be submitted the prior day and, pending approval, special passes were issued.

21. General Port Conditions From observations made from ship, the port appeared to be in a general state of retrograde and deterioration. No new construction or improvements were visible.

[Available on loan from the CIA Library is berth diagram referred to in paragraph 16 above, as well as overlay to HO Chart No 4197.]

- end -

25X1



CONFIDENTIAL [REDACTED]

25X1

25X1A

Approved For Release 2003/10/02 : CIA-RDP80-00926A007000010033-9

Next 3 Page(s) In Document Exempt

Approved For Release 2003/10/02 : CIA-RDP80-00926A007000010033-9